



Current



Windstar Entrance Plan View



Windstar Entrance






Existing



Windstar Entrance
Overall Wall Elevation


















WINDSTAR MAIN ENTRANCE REVISED COST PROJECTION WALL MODIFICATIONS Demolition OTY

March 8, 2021

Demolition	$\underline{\mathbf{OTY}}$		
 Column Caps 	10		
 Barrier/Logistics 	LS	5,000 x 2	\$10,000
 OMP 	4		
 Electrical 	LS		
Hardscape	I		
 Main Wall 	200 SF		
 Col. Stucco Paint 	8		
 Col. Raised 18" 	4	27,500 x 2	\$55,000
 Col. Capitols 	8		
 Wall Paint Stucco 	625 SF		
 MWLogo 			
 MW Clad Stone 	2000SF		
OM. Metal Panel Logos Signage Lighting	4 1 13	25,000 x 2	\$50,000
Total Soft Cost Contingency Total			\$115,000 \$ 15,000 \$ 20,000 \$150,000





March 8, 2021

WINDSTAR MAIN ENTRANCE
REVISED COST PROJECTION
LANDSCAPE MODIFICATION

LANDSCAPE MO	<u>DDIFICATION</u>	Landscape	F 17 2 4
Demolition			
 Sidewalk 	10O0SF ₃	2,500	
L andscapeGra din g	3 5000SF	5,000	
Irrigation (O.A.) 10),000SF	5,000	
Landscape			
`	5000SF,3000SF) (10,000SF)	52,500	
Sidewalk Lighting Total Soft Cost Contingency	10O0SF (15,10)	5,000 7,500 77,500 12,500 10,000	

\$100,000

Total

HARDSCAPE \$150,000 LANDSCAPE \$100,000 TOTAL \$250,000



<u>Plant Palette (and Alternatives)</u>







Dumbeya Tree Standard



TIBOUCHINA "Yesterday, Today & Tomorrow"



Small Leaf Clussia



Dwarf Variegated Arboricola



Green Island Ficus



Dwarf Carissa 'Emerald Blanket'



Flax Lily



Dwarf Asian Jasmine 'Sunset'



Bougainvillea Vine



Queen's Wreath

